


Bezeichnung	d x D mm	L <sub>1</sub> (mm)	L <sub>2</sub> (mm)	L <sub>3</sub> (mm)	B (mm)	D <sub>1</sub> (mm)	Übertragbares Drehmoment Mt (Nm)	Axialkraft F ax. (kN)	Flächenpressung Welle P <sub>w</sub> (N/mm <sup>2</sup> )	Flächenpressung Nabe P <sub>N</sub> (N/mm <sup>2</sup> )	Schrauben - Anzahl	Schrauben - Bezeichnung	Schrauben - Anzugsmoment Ms (Nm)	Gewicht (kg)	
<b>CE06</b>															
CE06 19	19x47	26	31	39	45	53	202	21	127	51	4	M6x20	17	0,45	
CE06 20	20x47	26	31	39	45	53	213	21	121	51	4	M6x20	17	0,46	
CE06 22	22x47	26	31	39	45	53	234	21	110	51	4	M6x20	17	0,50	
CE06 24	24x50	26	31	39	45	56	384	32	151	73	6	M6x20	17	0,50	
CE06 25	25x50	26	31	39	45	56	400	32	145	73	6	M6x20	17	0,50	
CE06 28	28x55	26	31	39	45	61	448	32	129	66	6	M6x20	17	0,60	
CE06 30	30x55	26	31	39	45	61	480	32	121	66	6	M6x20	17	0,60	
CE06 32	32x60	26	31	39	45	66	683	43	151	81	8	M6x20	17	0,70	
CE06 35	35x60	26	31	39	45	66	747	43	138	81	8	M6x20	17	0,60	
CE06 38	38x65	26	31	39	45	71	811	43	127	74	8	M6x20	17	0,80	
CE06 40	40x65	26	31	39	45	71	853	43	121	74	8	M6x20	17	0,60	
CE06 42	42x75	30	36	47	55	81	1216	58	135	76	6	M8x30	41	1,20	
CE06 45	45x75	30	36	47	55	81	1302	58	126	76	6	M8x30	41	1,10	
CE06 48	48x80	30	36	47	55	86	1389	58	119	71	6	M8x30	41	1,30	
CE06 50	50x80	30	36	47	55	86	1447	58	114	71	6	M8x30	41	1,10	
CE06 55	55x85	30	36	47	55	91	2124	77	138	89	8	M8x30	41	1,20	
CE06 60	60x90	30	36	47	55	96	2317	77	127	84	8	M8x30	41	1,30	
CE06 65	65x95	30	36	47	55	101	2510	77	117	80	8	M8x30	41	1,40	
CE06 70	70x110	40	46	57	67	116	4381	125	132	84	8	M10x35	83	2,50	
CE06 75	75x115	40	46	62	72	121	4694	125	123	80	8	M10x35	83	2,60	
CE06 80	80x120	40	46	62	72	126	5007	125	115	77	8	M10x35	83	2,80	
CE06 85	85x125	40	46	62	72	131	6651	156	136	92	10	M10x35	83	2,80	
CE06 90	90x130	40	46	62	72	136	7042	156	128	89	10	M10x35	83	3,00	
CE06 95	95x135	40	46	62	72	141	7433	156	121	85	10	M10x35	83	3,00	
CE06 100	100x145	46	52	77	89	151	9104	182	117	81	8	M12x45	145	5,50	
CE06 110	110x155	46	52	77	89	161	10015	182	106	75	8	M12x45	145	4,80	
CE06 120	120x165	46	52	77	89	171	13653	228	122	88	10	M12x45	145	5,50	
CE06 130	130x180	46	52	77	89	186	17747	273	135	97	12	M12x45	145	6,00	
CE06 140	140x190	51	59	84	98	196	17328	248	102	75	8	M14x45	230	7,50	
CE06 150	150x200	51	59	84	98	206	23207	309	119	89	10	M14x45	230	7,70	
CE06 160	160x210	51	59	84	98	216	24754	309	112	85	10	M14x45	230	8,00	
CE06 170	170x225	51	59	84	98	231	31561	371	126	95	12	M14x45	230	9,80	
CE06 180	180x235	51	59	84	98	241	33417	371	119	91	12	M14x45	230	9,80	












Bezeichnung	d x D mm	L <sub>1</sub> (mm)	B (mm)	D <sub>1</sub> (mm)	Übertragbares Drehmoment Mt (Nm)	Axialkraft F <sub>ax.</sub> (KN)	Flächenpressung Welle P <sub>w</sub> (N/mm <sup>2</sup> )	Flächenpressung Nabe P <sub>n</sub> (N/mm <sup>2</sup> )	Schrauben - Anzahl	Schrauben - Bezeichnung	Schrauben - Anzugsmoment Ms (Nm)	Gewicht (kg)
CE11												
CE11 15	15x25	20	31	32	77	9	91	55	1	M20x1	95	0,11
CE11 18	18x30	21	33	38	125	13	98	59	1	M25x1,5	160	0,13
CE11 19	19x30	21	33	38	132	13	93	59	1	M25x1,5	160	0,13
CE11 20	20x30	21	33	38	139	13	88	59	1	M25x1,5	160	0,15
CE11 24	24x35	25	38	45	202	15	74	51	1	M30x1,5	220	0,17
CE11 25	25x35	25	38	45	210	15	71	51	1	M30x1,5	220	0,17
CE11 28	28x40	28	44	52	312	20	76	53	1	M35x1,5	340	0,28
CE11 30	30x40	28	44	52	335	20	71	53	1	M35x1,5	340	0,26
CE11 32	32x45	28	45	58	483	25	75	58	1	M40x1,5	480	0,26
CE11 35	35x45	28	46	65	696	31	82	66	1	M45x1,5	680	0,33
CE11 40	40x50	28	47	70	902	36	84	69	1	M50x1,5	870	0,45
CE11 45	45x55	28	47	75	1014	37	77	64	1	M55x2	970	0,66
CE11 50	50x60	28	48	80	1158	38	73	61	1	M60x2	1100	0,72
CE11 60	60x70	28	50	85	1379	41	73	62	1	M65x2	1300	0,80




<b>CE13</b>													
Bezeichnung	d x D mm	L (mm)	L <sub>1</sub> (mm)	L <sub>2</sub> (mm)	L <sub>3</sub> (mm)	Übertragbares Drehmoment Mt (Nm)	Axialkraft F ax. (KN)	Flächenpressung Welle P <sub>w</sub> (N/mm <sup>2</sup> )	Schrauben - Anzahl	Schrauben - Bezeichnung	Schrauben - Anzugsmoment Ms (Nm)	Gewicht (kg)	
CE13 17	17x50	56	50	16	44	179	21	166	4	M6x45	17	0,51	
CE13 18	18x50	56	50	16	44	190	21	157	4	M6x45	17	0,52	
CE13 19	19x50	56	50	16	44	200	21	149	4	M6x45	17	0,50	
CE13 20	20x50	56	50	16	44	211	21	141	4	M6x45	17	0,50	
CE13 24	24x55	66	60	18,5	54	378	32	144	6	M6x55	17	0,71	
CE13 25	25x55	66	60	18,5	54	394	32	138	6	M6x55	17	0,69	
CE13 28	28x60	66	60	18,5	54	442	32	123	6	M6x55	17	0,81	
CE13 30	30x60	66	60	18,5	54	473	32	115	6	M6x55	17	0,78	
CE13 32	32x63	66	60	18,5	54	505	32	108	6	M6x55	17	0,85	
CE13 35	35x75	83	75	22	67	682	39	98	4	M8x70	42	1,48	
CE13 38	38x75	83	75	22	67	741	39	90	4	M8x70	42	1,45	
CE13 40	40x75	83	75	22	67	780	39	86	4	M8x70	42	1,40	
CE13 42	42x78	83	75	22	67	819	39	82	4	M8x70	42	1,50	
CE13 45	45x85	93	85	24,5	76	1317	59	101	6	M8x80	42	2,03	
CE13 48	48x90	93	85	24,5	76	1405	59	95	6	M8x80	42	2,24	
CE13 50	50x90	93	85	24,5	76	1463	59	91	6	M8x80	42	2,18	
CE13 55	55x94	93	85	24,5	76	2147	78	110	8	M8x80	42	2,29	
CE13 60	60x100	93	85	24,5	76	2343	78	101	8	M8x80	42	2,52	
CE13 65	65x105	93	85	24,5	76	2538	78	93	8	M8x80	42	2,69	
CE13 70	70x115	110	100	29	90	4321	123	116	8	M10x95	83	3,94	



Bezeichnung	$d_w$ (mm)	D (mm)	$L_1$ (mm)	$L_2$ (mm)	L (mm)	Flächen- pressung Welle $P_w$ (N/mm <sup>2</sup> )	Drehmo- ment M (Nm)	Axialkraft F (kN)	Schrauben - Anzahl	Schrauben - Bezeich- nung	Schrauben - Anzugs- moment M <sub>s</sub> (Nm)	Gewicht (kg)
<b>CE14</b>												
CE14 24	19	50	14	19,5	23	272	162	15,0	6	M5x18	4,9	0,20
	20						200	18,5				
	21						238	21,0				
CE14 30	24	60	16	21,5	25	221	285	15,7	7	M5x18	4,9	0,30
	25						323	23,7				
	26						361	26,7				
CE14 36	28	72	18	23,5	27,5	292	418	27,0	5	M6x20	11,8	0,40
	30						542	38,0				
	31						599	43,0				
CE14 44	32	80	20	25,5	29,5	301	589	44,0	7	M6x20	11,8	0,60
	35						741	49,0				
	36						817	54,0				
CE14 50	38	90	22	27,5	31,5	275	893	48,8	8	M6x25	11,8	0,80
	40						1102	58,8				
	42						1311	69,0				
CE14 55	42	100	23	30,5	34,5	239	1102	48,0	8	M6x25	11,8	1,10
	45						1444	61,7				
	48						1786	77,0				
CE14 62	48	110	23	30,5	34,5	265	1758	69,0	10	M6x25	11,8	1,30
	50						2090	80,9				
	52						2280	90,0				
CE14 68	50	115	23	30,5	34,5	242	1900	71,2	10	M6x25	11,8	1,40
	55						2375	80,9				
	60						2993	95,7				
CE14 75	55	138	25	32,5	37,8	259	2375	94,4	7	M8x30	29,4	1,70
	60						3040	111,0				
	65						3753	126,0				
CE14 80	60	145	25	32,5	37,8	243	3040	99,3	7	M8x30	29,4	1,90
	65						7505	115,0				
	70						4370	130,0				
CE14 90	65	155	30	39	44,3	257	4513	141,0	10	M8x35	29,4	3,30
	70						5700	160,0				
	75						6888	178,0				
CE14 100	70	170	34	44	49,3	245	6555	163,0	12	M8x35	29,4	4,70
	75						7125	182,0				
	80						8550	202,0				
CE14 110	75	185	39	50	56,4	232	6840	185,0	9	M10x40	57,8	5,90
	80						8550	207,0				
	85						10260	221,0				



Bezeichnung	d <sub>v</sub> (mm)	D (mm)	L <sub>1</sub> (mm)	L <sub>v</sub> (mm)	L (mm)	Flächen- pressung Welle P <sub>w</sub> (N/mm <sup>2</sup> )	Drehmo- ment M (Nm)	Axialkraft F (kN)	Schrauben - Anzahl	Schrauben - Bezeich- nung	Schrauben - Anzugs- moment M <sub>s</sub> (Nm)	Gewicht (kg)	
<b>CE14</b>													
CE14 125	85	215	42	54	60,4	253	10450	240,0	12	M10x40	57,8	8,30	
	90						12350	262,0					
	95						14250	285,0					
CE14 140	95	230	46	60,5	68	251	14345	308,0	10	M12x45	98	10,00	
	100						16720	331,0					
	105						19095	357,0					
CE14 155	105	265	50	64,5	72	250	20900	366,0	12	M12x50	98	15,00	
	110						23750	392,0					
	115						26600	417,0					
CE14 165	115	290	56	71	81	263	29450	513,0	8	M16x55	245	22,00	
	120						33250	544,0					
	125						37050	564,0					
CE14 175	125	300	56	71	81	248	34200	576,0	8	M16x55	250	22,00	
	130						38950	630,0					
	135						45000	666,0					



Bezeichnung	L <sub>1</sub> (mm)	L <sub>2</sub> (mm)	L <sub>3</sub> (mm)	B (mm)	D <sub>1</sub> (mm)	Über- tragbares Drehmo- ment Mt (Nm)	Axial- kraft F ax. (kN)	Flächen- pression Welle P <sub>w</sub> (N/mm <sup>2</sup> )	Flächen- pression Nabe P <sub>n</sub> (N/mm <sup>2</sup> )	Schrau- ben - Anzahl	Schrau- ben - Bezeich- nung	Schrau- ben - Anzugs- moment Ms (Nm)	Gewicht (kg)
<b>CE16</b>													
CE16 14 x 55	17	22	31	39	62	234	33	415	106	4	M8x25	37	0,50
CE16 16 x 55	17	22	31	39	62	268	33	363	106	4	M8x25	37	0,50
CE16 18 x 55	17	22	31	39	62	333	37	357	117	4	M8x25	41	0,50
CE16 19 x 55	17	22	31	39	62	352	37	338	117	4	M8x25	41	0,50
CE16 20 x 55	17	22	31	39	62	370	37	321	117	4	M8x25	41	0,50
CE16 22 x 55	17	22	31	39	62	407	37	292	117	4	M8x25	41	0,50
CE16 24 x 55	17	22	31	39	62	445	37	268	117	4	M8x25	41	0,50
CE16 25 x 55	17	22	31	39	62	463	37	257	117	4	M8x25	41	0,50
CE16 28 x 55	17	22	31	39	62	519	37	229	117	4	M8x25	41	0,40
CE16 30 x 55	17	22	31	39	62	556	37	214	117	4	M8x25	41	0,40
CE16 24 x 65	17	22	31	39	72	556	46	335	124	5	M8x25	41	0,70
CE16 25 x 65	17	22	31	39	72	579	46	321	124	5	M8x25	41	0,70
CE16 28 x 65	17	22	31	39	72	649	46	287	124	5	M8x25	41	0,60
CE16 30 x 65	17	22	31	39	72	695	46	268	124	5	M8x25	41	0,60
CE16 32 x 65	17	22	31	39	72	741	46	251	124	5	M8x25	41	0,60
CE16 35 x 65	17	22	31	39	72	811	46	230	124	5	M8x25	41	0,50
CE16 38 x 65	17	22	31	39	72	880	46	211	124	5	M8x25	41	0,50
CE16 40 x 65	17	22	31	39	72	927	46	201	124	5	M8x25	41	0,50
CE16 30 x 80	20	25	33	41	87	972	65	318	119	7	M8x25	41	1,00
CE16 32 x 80	20	25	33	41	87	1037	65	299	119	7	M8x25	41	1,00
CE16 35 x 80	20	25	33	41	87	1134	65	273	119	7	M8x25	41	1,00
CE16 38 x 80	20	25	33	41	87	1231	65	251	119	7	M8x25	41	1,00
CE16 40 x 80	20	25	33	41	87	1296	65	239	119	7	M8x25	41	0,90
CE16 42 x 80	20	25	33	41	87	1361	65	227	119	7	M8x25	41	0,90
CE16 45 x 80	20	25	33	41	87	1458	65	212	119	7	M8x25	41	0,80
CE16 48 x 80	20	25	33	41	87	1555	65	199	119	7	M8x25	41	0,80
CE16 50 x 80	20	25	33	41	87	1620	65	191	119	7	M8x25	41	0,80