

SUCCESS STORY

RED POWER



INDUSTRY

HVAC

APPLICATION

Cooling Tower

COMPANY PROFILE

Large Casino and Resort

PROBLEM

The belts on cooling towers at a large Las Vegas casino were stretching and failing after only 6 months of operation. The cooling towers were difficult to access and servicing the towers would take nearly an entire day. The casino was looking to cut maintenance costs and at the time were paying over \$4000 per year on belts and installation on each tower.

SOLUTION

RED POWER Banded B173

RESULTS

RED POWER directly replaced the existing banded belt. RED POWER's maintenance-free construction improved the belt life to over 18 months on average saving the customer thousands of dollars a year in maintenance.